



PRODUCT OBSOLESCENCE MEMO

MAGNETICS



Bourns® Model 9220, RL187, RL262 and RL855 Series Axial/Radial Inductors to be Discontinued

Riverside, California – November 18, 2022 - In accordance with our ongoing product life cycle management procedure, Bourns will transfer the Model [9220](#), [RL187](#), [RL262](#), and [RL855](#) Series Axial/Radial Lead Inductors to an End of Product Life status. A lack of sales volume and diminishing demand necessitates this action.

Regrettably, no replacement part numbers are available at this time. Customers may continue to purchase these part numbers during the End of Product Life transition period between now and March 6, 2023. Orders for these part numbers during this End of Product Life transition period will be considered noncancellable. Products purchased during this End of Product Life transition period will be considered nonreturnable and will be covered by Bourns' standard warranty.

Please plan for the following deadlines:

Last time buy date: **March 6, 2023**

Last time ship date: **September 6, 2023**

A list of affected part numbers is provided below:

Affected Part Numbers						
9220-00-RC	9220-28-RC	RL187-271J-RC	RL262-101J-RC	RL262-332J-RC	RL855-102K-RC	RL855-332K-RC
9220-02-RC	RL187-101J-RC	RL187-272J-RC	RL262-102J-RC	RL262-391J-RC	RL855-103K-RC	RL855-390K-RC
9220-04-RC	RL187-102J-RC	RL187-273J-RC	RL262-103J-RC	RL262-392J-RC	RL855-121K-RC	RL855-391K-RC
9220-06-RC	RL187-103J-RC	RL187-331J-RC	RL262-121J-RC	RL262-471J-RC	RL855-122K-RC	RL855-392K-RC
9220-08-RC	RL187-121J-RC	RL187-332J-RC	RL262-122J-RC	RL262-472J-RC	RL855-151K-RC	RL855-470K-RC
9220-10-RC	RL187-122J-RC	RL187-333J-RC	RL262-123J-RC	RL262-561J-RC	RL855-152K-RC	RL855-471K-RC
9220-12-RC	RL187-123J-RC	RL187-391J-RC	RL262-151J-RC	RL262-562J-RC	RL855-181K-RC	RL855-472K-RC
9220-14-RC	RL187-151J-RC	RL187-392J-RC	RL262-152J-RC	RL262-681J-RC	RL855-182K-RC	RL855-560K-RC
9220-15-RC	RL187-152J-RC	RL187-471J-RC	RL262-153J-RC	RL262-682J-RC	RL855-220K-RC	RL855-561K-RC
9220-16-RC	RL187-153J-RC	RL187-472J-RC	RL262-181J-RC	RL262-821J-RC	RL855-221K-RC	RL855-562K-RC
9220-18-RC	RL187-181J-RC	RL187-561J-RC	RL262-182J-RC	RL262-822J-RC	RL855-222K-RC	RL855-680K-RC
9220-20-RC	RL187-182J-RC	RL187-562J-RC	RL262-221J-RC	RL855-100M-RC	RL855-270K-RC	RL855-681K-RC
9220-22-RC	RL187-183J-RC	RL187-681J-RC	RL262-222J-RC	RL855-120M-RC	RL855-271K-RC	RL855-682K-RC
9220-22-TR-RC	RL187-221J-RC	RL187-682J-RC	RL262-271J-RC	RL855-150M-RC	RL855-272K-RC	RL855-820K-RC
9220-24-RC	RL187-222J-RC	RL187-821J-RC	RL262-272J-RC	RL855-180M-RC	RL855-330K-RC	RL855-821K-RC
9220-26-RC	RL187-223J-RC	RL187-822J-RC	RL262-331J-RC	RL855-101K-RC	RL855-331K-RC	RL855-822K-RC

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

IC22135