



PRODUCT OBSOLESCENCE MEMO

SINGL FUSE™ SMD FUSES



Bourns® Model SF-2923UC-C Series to be Discontinued

Riverside, California – February 19, 2021 – Effective immediately, Bourns is discontinuing the Model [SF-2923UC-C](#) SinglFuse™ Ultra-High Current SMD Fuse Series. Unfortunately, Bourns is unable to support any Last Time Buy orders as part of this product obsolescence. The discontinued part numbers and alternative Bourns part numbers for consideration can be found in the table below.

Obsolete Part Numbers	Alternative Part Numbers to Consider
SF-2923UC20C-2	SF-2923HC20C-2
SF-2923UC30C-2	SF-2923HC30C-2
SF-2923UC40C-2	SF-2923HC40C-2
SF-2923UC50C-2	SF-2923HC50C-2
SF-2923UC60C-2	SF-3812F6000T-2
SF-2923UC80C-2	none
SF-2923UC100C-2	none

Customers may notify Bourns in writing if they consider any of the discontinued products to be sole sourced by Bourns. In such cases, Bourns will work with customers to help them find a suitable replacement, even if the replacement is not a Bourns® product.

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).

MF2108