

BOURNS®

Product Update Memo

INDUCTIVE COMPONENTS

October, 2006

Bourns Manufacturers Representatives
Corporate Distributor Product Managers
Americas Sales Team
Asia Sales Team
Europe Sales Team
Bourns Internal
Bourns Plant Managers

Bourns® / JW Miller P/N B4257 Discontinued

The materials required to manufacture the axial-leaded inductor part number B4257 are no longer available. Consequently, Bourns must discontinue this custom-designed part effective immediately.

IC0641