

Product Obsolescence Memo

INDUCTIVE COMPONENTS

April, 2016

Bourns® Model 4588-RC Axial Lead RF Choke to be Discontinued

Bourns has decided to discontinue the Model 4588-RC Axial Lead RF Choke. A lack of sales volume and diminishing demand necessitates this action. Regrettably, no replacement part number is available at this time.

Obsolete Part Number: 4588-RC

Please plan for the following deadlines:

Last time buy date: October 8, 2016

Last time ship date: April 8, 2017

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).