

**BOURNS®**

# Product Update Memo

**INDUCTIVE COMPONENTS**

August, 2006

Bourns Manufacturers Representatives  
Corporate Distributor Product Managers  
Americas Sales Team  
Asia Sales Team  
Europe Sales Team  
Bourns Internal  
Bourns Plant Managers

## **Bourns® Inductive Components Product Line Discontinues PMC1806 and PMC1812 Series; PMH1806 and PMH1812 Series Replaced by MH4516 and MH4532**

Effective immediately Bourns® Inductive Components Product Line is discontinuing chip bead Models PMC1806 and PMC1812. This decision was prompted by lack of sales for these models.

Additionally, chip bead Models PMH1806 and PMH1812 are being discontinued. Most of the part numbers for these two models have existing Bourns equivalents.

<b>JW Miller P/N</b>	<b>Bourns P/N (or nearest equivalent)</b>
PMH1806-500	None
PMH1806-600	MH4516-600Y
PMH1816-700	MH4516-750Y
PMH1806-800	None
PMH1806-101	None
PMH1812-121	MH4532-121Y
PMH1812-151	MH4532-151Y
PMH1812-501	None
PMH1812-681	MH4532-681Y