


Product Obsolescence Memo

CIRCUIT PROTECTION PRODUCTS



Issued December, 2016
Revised January, 2019


Bourns® Model B0500T, B1250T and B2000T Telefuse™ SMD Power Cross Protection Fuse Products Discontinued

- Recommended Replacement Products Now Available -

In accordance with our ongoing product lifecycle management procedure, Bourns identified select Telefuse™ SMD Power Cross Protection Fuse products to be transferred to an End of Product Life status.

Bourns discontinued the [Model B0500T, B1250T and B2000T Telefuse™ SMD Power Cross Protection Fuse Products](#) listed below with an effective date of June 30, 2017. Products purchased during this End of Product Life transition period were covered by Bourns' standard warranty. Last Time Buy orders for these products were considered non-cancellable and non-returnable.

December, 2018 Update: Recommended replacement products are now available. The replacement devices are functionally equivalent and are pin-to-pin compatible. Please contact the Bourns team of Field Application Engineers if you have any questions regarding the suggested replacement parts and your application requirements.



Obsolete Part Numbers	Recommended Replacement Part Numbers
B0500T	SF-3812TM050T-2
B1250T	SF-3812TM125T-2
B2000T	SF-3812TM200T-2



Please plan for the following deadlines:

Last time buy date: June 30, 2017

Last time ship date: December 31, 2017

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).