


Product Obsolescence Memo

PRECISION POTENTIOMETERS



October 17, 2018

Bourns® Model 3751H-432-103 Precision Potentiometer to be Discontinued

In accordance with our ongoing product lifecycle management procedure, Bourns has transferred the [Bourns® Model 3751H-432-103](#) Precision Potentiometer to an End of Product Life status.

Recommended replacement products are available. The replacement devices are functionally equivalent and pin-to-pin compatible. Please note the replacement parts will not have a clutch. Please contact the [Bourns team of Field Application Engineers](#) if you have any questions regarding the suggested replacement parts and your application requirements.

Bourns is discontinuing the Model 3751H-432-103 with an effective date of December 30, 2018. Products purchased during this End of Product Life transition period will be covered by Bourns' standard warranty. Last Time Buy orders for these products will be considered non-cancellable and non-refundable.

Obsolete Part Number	Recommended Replacement Part Numbers
3751H-432-103	3751H-600-103L 3751H1-1-103L

Please plan for the following deadlines:

*Last time buy date: **December 30, 2018***

*Last time ship date: **December 20, 2019***

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).

SC1839