

Certificate of Approval

This is to certify that the Management System of:

Bourns, Inc., Trimpot Electronics Ltda.

150 Metros Oeste del Cruce Autopista General Canas San Antonio de Belen, Costa Rica

has been approved by Lloyd's Register to the following standards:

IATF 16949:2016

Approval number(s): IATF 16949 – 0078231-001

This certificate is valid only in association with the certificate schedule bearing the same number on which the locations applicable to this approval are listed.

The scope of this approval is applicable to:

Design and Manufacture of Resistor Networks and Power Resistors.



Cliff Muckleroy

Area Operations Manager Americas

Issued by: Lloyd's Register Quality Assurance Limited



Certificate Schedule

| Location | Activities |
|---|---|
| 1200 Columbia Avenue, Riverside, CA, 92507, United States | IATF 16949:2016 Contract Review, Customer Service, Laboratory, and Testing. |
| 1 Kung 6th Road, Lin-Kou District, New Taipei City, ROC, Taiwan | IATF 16949:2016 Testing. DQS Certificate # 20000419 IATF-16 |

