## BOURNS

## **Product Change/Obsolescence Notification**

TRIMPOT<sup>®</sup> PRODUCTS



June, 2013

## **Bourns® Trimpot® Products**

In July 2012, Bourns Trimpot Product Line announced the move of the manufacturing location for non-wirewound trimmer and modular contact Bourns<sup>®</sup> products in Product Change Notification (PCN) number T1214. Associated with the manufacturing moves announced in PCN T1214 was the move or obsolescence of certain associated hardware products and design kits. At this time, Bourns is confirming the new manufacturing locations or obsolescence for the hardware and design kits listed below. There is no change to the form, fit or function of the hardware as a result of the change in manufacturing location for the listed hardware products.

Hardware Part Number	New Manufacturing Location	Date Moved to New Plant
H-28	Costa Rica	0ct. 2012
H-82	Costa Rica	0ct. 2012
H-83P	Costa Rica	0ct. 2012
H-117P	Costa Rica	0ct. 2012
H-115P	Costa Rica	0ct. 2012
H-25	Costa Rica	Nov. 2012
H-65P-1	Costa Rica	Nov. 2012
H-58P	Costa Rica	Nov. 2012
H-114P	Costa Rica	Jan. 2013
H-116P	Costa Rica	Jan. 2013

Design Kit Part Number	New Manufacturing Location	Date Moved to New Plant
H-814-2	Obsolete	Mar. 2012
H-840	Obsolete	Mar. 2012
H-839	Taiwan	Jan. 2013
H-843	Taiwan	Jan. 2013
H-851	Costa Rica	Jan. 2013

Should you have any questions of need additional information, please feel free to contact Customer Service/Inside Sales.