


PRODUCT OBSOLESCENCE MEMO

MAGNETICS



Bourns® FB2000, RL875, RL875S, and RLH0912 Series Chokes and Radial Inductors to be Discontinued

Riverside, California — October 30, 2025 — In accordance with our ongoing product life cycle management procedure, effective January 1, 2026, Bourns will transfer the FB2000, RL875, RL875S, and RLH0912 Series Chokes and Radial Inductors to an End of Product Life status. A lack of sales volume and diminishing demand necessitates this action. A list of obsolete part numbers is included below.

		Obsolete Part Numbers:		
FB20009-3B-RC	RL875-220K-RC	RL875-682K-RC	RL875S-330L-RC	RLH0912-101KBRL
				RLH0912-101KL
FB20010-3B-RC	RL875-221K-RC	RL875-820K-RC	RL875S-331K-RC	
<u>FB20011-3B-RC</u>	RL875-222K-RC	<u>RL875-821K-RC</u>	RL875S-332K-RC	RLH0912-102KBRL
<u>FB20019-4B-RC</u>	<u>RL875-270K-RC</u>	RL875-822K-RC	RL875S-390L-RC	RLH0912-102KL
FB20020-4B-RC	RL875-271K-RC	RL875S-100L-RC	RL875S-391K-RC	RLH0912-150KL
FB20021-4B-RC	RL875-272K-RC	RL875S-101K-RC	RL875S-392K-RC	RLH0912-151KL
FB20022-4B-RC	RL875-330K-RC	RL875S-102K-RC	RL875S-470L-RC	RLH0912-1R5ML
RL875-100M-RC	RL875-331K-RC	RL875S-103K-RC	RL875S-471K-RC	RLH0912-220KL
RL875-101K-RC	RL875-332K-RC	RL875S-121K-RC	RL875S-472K-RC	RLH0912-221KL
RL875-102K-RC	RL875-390K-RC	RL875S-122K-RC	RL875S-560K-RC	RLH0912-2R2ML
RL875-103K-RC	RL875-391K-RC	RL875S-151K-RC	RL875S-561K-RC	RLH0912-330KL
RL875-120M-RC	RL875-392K-RC	RL875S-152K-RC	RL875S-562K-RC	RLH0912-331KL
RL875-121K-RC	RL875-470K-RC	RL875S-181K-RC	RL875S-680K-RC	RLH0912-3R3ML
RL875-122K-RC	RL875-471K-RC	RL875S-182K-RC	RL875S-681K-RC	RLH0912-470KL
RL875-150K-RC	RL875-472K-RC	RL875S-220L-RC	RL875S-682-KC	RLH0912-471KL
RL875-151K-RC	RL875-560K-RC	RL875S-221K-RC	RL875S-682K-RC	RLH0912-4R7ML
RL875-152K-RC	RL875-561K-RC	RL875S-222K-RC	RL875S-820K-RC	RLH0912-680KL
RL875-180K-RC	RL875-562K-RC	RL875S-270L-RC	RL875S-821K-RC	RLH0912-681KL
RL875-181K-RC	RL875-680K-RC	RL875S-271K-RC	RL875S-822K-RC	RLH0912-6R8ML
RL875-182K-RC	RL875-681K-RC	RL875S-272K-RC	RLH0912-100KL	

IC25187



Regrettably, no replacement part numbers are available at this time. Customers may continue to purchase these part numbers during the End of Product Life transition period between now and January 1, 2026. Orders for these part numbers during this End of Product Life transition period will be considered noncancellable. Products purchased during this End of Product Life transition period will be considered nonreturnable and will be covered by Bourns' standard warranty.

Please plan for the following deadlines:

Last time buy date: *January 1, 2026*Last time ship date: *June 1, 2026*

If you have any questions or need additional information, please feel free to contact Customer Service/Inside Sales.