

Product Obsolescence Memo

TRANSFORMERS

Bourns Manufacturers Representatives Corporate Distributor Product Managers Americas Sales Team Asia Sales Team Europe Sales Team Bourns Internal Bourns Plant Managers

February, 2010

Model 4210, 4212 Micro Transformers and 4260-1647 Data Bus Interface Transformers Discontinued

Effective immediately, Model 4210-xxxx, 4212-xxxx Micro Transformers and Model 4260-1647-xx MIL-STD-1553 Data Bus Interface Transformers have been discontinued. These three transformer models have received very low sales activity for a prolonged period. A lack of sales volume and diminishing demand for these products necessitate this action.

Affected part numbers:

4210-0010 through 4210-0030 4212-0001 through 4212-0019 4260-1647-00 through 4260-1647-33