


Product Obsolescence Memo

TRANSFORMERS



February, 2014

Bourns® Model SM75056 and SM75057 T1/E1 Transformers to be Discontinued

Bourns will be discontinuing the Model SM75057 and SM75056 family of T1/E1 Transformers due to a lack of sales volume and diminishing demand. The obsolete part numbers and the suggested replacement part numbers are listed below.

The form, fit and function of suggested replacement transformers are not identical to the obsolete parts. However, their specifications are likely to be substitutable for the typical applications. Please refer to the Bourns data sheets for additional details.

Obsolete Part Numbers	Suggested Replacement
SM75056E	SM75056PEL
SM75056EL	SM75056PEL
SM75057	SM75057PEL
SM75057E	SM75057PEL
SM75057EL	SM75057PEL

Please plan for the following deadlines:

Last time buy date: August 22, 2014

Last time ship date: November 30, 2014

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).