

Product Obsolescence Memo

CERAMIC PTC RESETTABLE FUSES



July 12, 2018

Select Bourns® Ceramic PTC Resettable Fuses to be Discontinued

Bourns has decided to discontinue select Ceramic PTC Resettable Fuses. A lack of sales volume and diminishing demand necessitates this action. The suggested alternative part numbers, last time buy date, and last time ship date are listed in the table below.

Please contact the [Bourns team of Field Application Engineers](#) if you have any questions regarding the suggested replacement part numbers and your application requirements.

Obsolete Part Number	Suggested Alternative Part Number	Last Time Buy	Last Time Ship
CMF-RLC50-0	CMF-RL series	12/31/2018	12/31/2019
CMF-RLC50-10-0			
CMF-RD50-0	CMF-SDP Series	12/31/2018	12/31/2019
CMF-RD50-10-0			
CMF-RQ50-0	None	12/31/2018	12/31/2019
CMF-RQ50-10-0			
CMF-SD10-2	CMF-SDP Series	12/31/2018	12/31/2019
CMF-SD25-2			
CMF-SD25-10-2			
CMF-SD25A-2			
CMF-SD25A-10-2			
CMF-SD35-0			
CMF-SD35-2			
CMF-SD35-10-2			
CMF-SD35A-2			
CMF-SD35A-10-2			
CMF-SD50-0			
CMF-SD50-2			
CMF-SD50-10-2			
CMF-SD50A-2			
CMF-SD50A-10-2			

Should you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).

MF1812