

## Product Obsolescence Memo

### OSP PRODUCTS



January, 2016

### **Bourns® Model 3617-01 and 3617-02 to be Discontinued**

Bourns has decided to discontinue the [Model 3617-01 Series](#) DSL Splitter with Integrated Balance-Unbalance (BalUn) Adapter and the [Model 3617-02](#) VDSL-POTS Splitter-Filter-BalUn. A lack of sales volume and diminishing demand necessitates this action.

There are no direct replacement part numbers available; however, substituting [Model 3610V2](#) in combination with [Model 3670-01](#) provides the same main functions as the discontinued part numbers. The substitute part numbers take up more space in the Network Interface Device (NID) and do not contain a test jack. Please contact the Bourns team of Field Application Engineers if you have any questions regarding the suggested replacement parts and your application requirements.

Obsolete Part Numbers	Suggested Replacement Part Numbers (1 Each)
3617-01	3610V2
3617-02	3670-01

Please plan for the following deadlines:

*Last time buy date: July 20, 2016*

*Last time ship date: January 20, 2017*

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).