

## Product Obsolescence Memo

UNINTERRUPTIBLE POWER SUPPLIES



October, 2016

### Bourns® Indoor UPS Series MP1218 and MX1236 *and* Outdoor UPS Series U01 and U02 Discontinued

Bourns has decided to discontinue the Indoor UPS Series [MP1218-L1, -P](#) and [MX1236](#), and Outdoor UPS Series [U01](#) and [U02](#), effective immediately. A lack of sales volume and diminishing demand necessitates this action. Regrettably, no replacement part numbers are available at this time.

#### Obsolete Part Numbers

Indoor UPS	Outdoor UPS
MP1218-L1-C2	U01120-050-120-A
MP1218-L1-C7	U01120-050-120-AH
MP1218-P-C2	U01120-084-120-A
MP1218-P-C7	U01120-084-120-AH
MP18-L1	U01120-105-120-B
MX1236-L2-C7	U01120-105-120-BH
MX1236-P-C7	U02120-006-12-A
MX36-L2	U02120-006-12-AH
	U02120-010-24-B
	U02120-010-24-BH
	U02120-015-12-B
	U02120-015-12-BH
	U02120-015-24-B
	U02120-015-24-BH

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).