## BOURNS

# **Product Obsolescence Memo**

### PANEL CONTROLS



June, 2015

## Selected Bourns<sup>®</sup> Model 3862 1/2 " Diameter Single-Turn Panel Controls to be Discontinued

In line with our commitment to provide our customers with exceptional value, Bourns Sensors & Controls is announcing the discontinuance of selected low resistance values from our Model 3862 1/2" Diameter Single-Turn Panel Controls. A lack of market demand and increasing production costs have prompted the obsolescence of this model with the following resistance values: 100  $\Omega$ , 250  $\Omega$ , and 500  $\Omega$ 

This notification affects both standard and modified standard part numbers with the select resistance values. Effective immediately, samples will no longer be available for these select resistance values. Regrettably, no replacement part numbers are available at this time.

3862C-122-101AL	3862C-202-501AL
3862C-122-501AL	3862C-282-101AL
3862C-162-101AL	3862C-282-501AL
3862C-162-251AL	3862C-286-251AL
3862C-162-501AL	3862E-202-101AL
3862C-202-101AL	3862E-202-251AL

#### **Obsolete Part Numbers:**

Please plan for the following deadlines:

*Last time buy date: December 1, 2015 Last time ship date: January 1, 2016* 

Should you have any questions or need additional information, please feel free to contact Customer Service/Inside Sales.