



# Product Obsolescence Memo

## CIRCUIT PROTECTION PRODUCTS

Bourns Manufacturers Representatives  
Corporate Distributor Product Managers  
Americas Sales Team  
Asia Sales Team  
Europe Sales Team

June, 2010

### Overvoltage Protection - TSP Products - SOT82 Packaging

Effective immediately, the following TSP products have been discontinued due to diminished demand:

| <b>Bourns Obsolete Part Number</b> | <b>Package</b> |
|------------------------------------|----------------|
| IDM1L-S                            | SOT82          |
| R3463L-S                           | SOT82          |
| R3490L-S                           | SOT82          |
| R3506L-S                           | SOT82          |
| R3547L-S                           | SOT82          |
| R3560L-S                           | SOT82          |
| R3563L-S                           | SOT82          |
| TISP1082L-S                        | SOT82          |
| TISP2082L-S                        | SOT82          |
| TISP2180L-S                        | SOT82          |
| TISP2180LT-S                       | SOT82          |
| TISP2290L-S                        | SOT82          |
| TISP2300L-S                        | SOT82          |
| TISP2310L-S                        | SOT82          |
| TISP3082L-S                        | SOT82          |
| TISP3180L-S                        | SOT82          |
| TISP3290L-S                        | SOT82          |
| Y1112L-S                           | SOT82          |
| Y1181L-S                           | SOT82          |
| Y1112-PS77                         | SOT82          |