


Product Obsolescence Memo

ROTARY POSITION SENSORS



September, 2012

Bourns Industrial Division Discontinues Model TC88 Rotary Position Sensor

Bourns Industrial Division announces the end of life for Bourns® [Model TC88 Rotary Position Sensor](#). A lack of sales volume and diminishing demand necessitates this action.

At this time, we are asking that customers assess their requirements and plan for last time buy orders in accordance with the following dates:

*Deadline for accepting final orders: **October 31, 2012***

*Final shipments to be made by: **December 15, 2012***

All orders placed will be considered NC/NR and may not be scheduled out.

[Bourns® Rotary Position Sensor Model 3382G-1-\(RC\)](#) is the recommended alternate model. Model 3382 has a much longer rotational life (1,000,000 cycles), and is available in six standard resistance codes and two shaft diameter hole sizes.

Samples of Model 3382 are readily available and are stocked at several distributors.

Should you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).