




Product Change Notification

May, 2008

Bourns Manufacturers Representatives
Corporate Distributor Product Managers
Americas Sales Team
Asia Sales Team
Europe Sales Team
Bourns Internal
Bourns Plant Managers



Model 78F - Change in Color

Effective immediately, the color of the coating material used in [Model 78F](#), a radial lead inductor, will be changed to blue (from the current color of burgundy).



New Color



Former Color

Model 78F will still be RoHS compliant. There is NO CHANGE in performance, dimensions, or packaging.

A list of affected part numbers is located on page 2 of this memo

IC0828

Model 78F - Part Numbers

78F100J-RC	78F470J-RC
78F101J-RC	78F471J-RC
78F102J-RC	78F4R7J-RC
78F120J-RC	78F560J-RC
78F121J-RC	78F561J-RC
78F150J-RC	78F5R6J-RC
78F151J-RC	78F680J-RC
78F180J-RC	78F681J-RC
78F181J-RC	78F6R8J-RC
78F1R0K-RC	78F820J-RC
78F1R2K-RC	78F821J-RC
78F1R5K-RC	78F8R2J-RC
78F1R8K-RC	78FR033M-RC
78F220J-RC	78FR10M-RC
78F221J-RC	78FR12M-RC
78F270J-RC	78FR15M-RC
78F271J-RC	78FR18M-RC
78F2R2K-RC	78FR22K-RC
78F2R7K-RC	78FR27K-RC
78F330J-RC	78FR33K-RC
78F331J-RC	78FR39K-RC
78F390J-RC	78FR47K-RC
78F391J-RC	78FR56K-RC
78F3R3J-RC	78FR68K-RC
78F3R9J-RC	78FR82K-RC