


Product Change Notification

INDUCTIVE COMPONENTS



December, 2016

Changes to Bourns Part Numbers 70F101AF-RC and 70F502AF-RC Varnished Chokes

Bourns is announcing the following changes to the part numbers [70F101AF-RC](#) and [70F502AF-RC](#) Varnished Chokes.

- 1) **Manufacturing Location:** Products are being transferred from Guangdong, China to Xiamen, China.
- 2) **Materials:** The core material currently being used on these two part numbers will be discontinued. An equivalent replacement material will be used to produce these two parts. Other materials will be adjusted accordingly, as well.
- 3) **Lead Length:** Component lead length will be changed from 1.25 " nominal to 1.18 " minimum.
- 4) **MOQ/Mult:** As a result of this change, the Minimum Order Quantity (MOQ) / Multiples quantity (Mult) will be adjusted. For your convenience, Table 1 shows the differences in quantity.

There will be a change to the fit (lead length). There will be no change to the form, function, quality or reliability of the varnished choke.

Table 1		
Affected Part Numbers	MOQ/Mult	
	Current	Revised
70F101AF-RC	264 / 132	600 / 600
70F502AF-RC	408 / 204	600 / 600

Implementation dates are as follows:

Date that manufacturing of existing products will cease: February 4, 2017

Date that deliveries of modified products will begin: February 5, 2017

First date code using the above changes: 1706

Product samples will be available upon request.

If you have any questions or need additional information, please feel free to contact [Customer Service/ Inside Sales](#).