




Product Change Notification

RESISTOR NETWORKS

Bourns Manufacturers Representatives
Corporate Distributor Product Managers
Americas Sales Team
Asia Sales Team
Europe Sales Team
Bourns Internal
Bourns Plant Managers



March, 2010

Bourns Adds Second Manufacturing Location

Bourns is adding a second manufacturing location in China for the 4600 Series resistor networks to increase capacity and delivery support to our customers.

The models affected are as follows:

Bourns® Model	Bourns® Model
4600X-101/102/104-RCLF	4600H-701/702-RCLF
4600M-101/102/104-RCLF	4600M-901/902-RCLF
4600H-101/102/104-RCLF	4600M-AP1/AP2/AP4-RCLF
4600X-AP1/AP2/AP4-RCLF	4600H-AP1/AP2/AP4-RCLF

Reliability data, SGS and MDS reports on the units will be available on or before April 23, 2010.

Deliveries from the new factory will begin on April 23, 2010.

Changes to Data Sheets

Parameter	Current Specification	New Specification
Resistance to Soldering Heat	$\Delta R \pm 0.25 \%$	$\Delta R \pm 0.5 \%$
Pin Length (mm)	3.43 +0.38 / -0.508	3.3 +0.5 / -0.3