




# PRODUCT OBSOLESCENCE MEMO

## TISP® THYRISTOR SURGE PROTECTORS



### **Bourns® Model TISP8250DR-S Overvoltage / Overcurrent Protector and Select Model R3xxx Series TISP® Thyristor Surge Protectors to be Discontinued**

Riverside, California – April 13, 2023 - In accordance with our ongoing product life cycle management procedures, effective immediately, Bourns will transfer the [Model TISP8250DR-S Overvoltage and Overcurrent Protector](#) and several Model R3xxx Series custom part numbers, only as shown in the table below, to an End of Product Life status. A lack of sales volume and diminishing demand necessitates this action.

A list of obsolete part numbers is provided below.

Obsolete Part Numbers			
TISP8250DR-S	R3400	R3403	R3424
R3337	R3401	R3404	R3425
R3383	R3402	R3406	R3490

Regrettably, no replacement part numbers are available at this time.

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

TSP2301