




PRODUCT OBSOLESCENCE MEMO

MAGNETICS

REVISED October 18, 2022



Bourns® Model PM1008S Series Shielded Wirewound Chip Inductors to be Discontinued

Riverside, California – October 10, 2022 – In accordance with our ongoing product life cycle management procedure, Bourns will transfer the [Model PM1008S Series Shielded Wirewound Chip Inductors](#) to an End of Product Life status. A lack of sales volume and diminishing demand necessitates this action. A list of affected part numbers is provided below.

Affected Part Numbers		
PM1008S-1R0M-RC	PM1008S-150M-RC	PM1008S-151M-RC
PM1008S-1R5M-RC	PM1008S-220M-RC	PM1008S-221M-RC
PM1008S-1R8M-RC	PM1008S-330M-RC	PM1008S-331M-RC
PM1008S-2R7M-RC	PM1008S-390M-RC	PM1008S-471M-RC
PM1008S-3R9M-RC	PM1008S-470M-RC	PM1008S-561M-RC
PM1008S-4R7M-RC	PM1008S-680M-RC	PM1008S-681M-RC
PM1008S-5R6M-RC	PM1008S-820M-RC	PM1008S-821M-RC
PM1008S-6R8M-RC	PM1008S-101M-RC	PM1008S-102M-RC
PM1008S-100M-RC	PM1008S-121M-RC	

Regrettably, no replacement part numbers are available at this time. Customers may continue to purchase these part numbers during the End of Product Life transition period between now and **March 31, 2023**. Orders for these part numbers during this End of Product Life transition period will be considered noncancellable. Products purchased during this End of Product Life transition period will be considered nonreturnable and will be covered by Bourns' standard warranty.

Please plan for the following deadlines:

Last time buy date: **March 31, 2023**

Last time ship date: **September 30, 2023**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

IC22122REV