


BOURNS®

Product Update Memo

July, 2006

Bourns Manufacturers Representatives
Corporate Distributor Product Managers
Americas Sales Team
Asia Sales Team
Europe Sales Team
Bourns Internal
Bourns Plant Managers



Trimmer Distributor Product Definition Change

Bourns® Trimpot® Division is pleased to announce a distributor product definition change on select resistance values of models 3266, 3269, 3296, 3299, 3306, 3309, 3314, 3352, 3361, 3362, 3364 and 3386. The change from a C to an A status was made to promote growth in our newest models and to improve our position with existing models. The additions are highlighted in Figure 1.

Trimmer Distributor Product Definition Change

July, 2006

Page 3 of 3

MODEL	1 0 0	2 0 0	5 0 0	1 0 1	2 0 1	5 0 1	1 0 2	2 0 2	5 0 2	1 0 3	2 0 3	2 5 3	5 0 3	1 0 4	2 0 4	2 5 4	5 0 4	1 0 5	2 0 5	5 0 5	
3352T										A				A							
3361P						A		A	A	A	A										
3361S										A											
3362H						A	A	A	A	A	A	A	A								
3362P				A	A	A	A	A	A	A	A		A	A		A					
3362W				A	A	A	A	A	A	A	A		A	A							
3362X						A	A	A	A	A	A		A	A							
3362R										A											
3364W										A											
3386B					A	A	A	A	A	A	A										
3386C						A	A	A	A	A	A	A					A				
3386F			A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A			
3386H				A		A	A	A	A	A	A	A	A	A	A		A				
3386P			A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	A	
3386W		A	A	A	A	A	A	A	A	A	A	A	A	A			A	A			
3386X				A	A	A	A	A	A	A	A		A	A	A	A	A	A			
RJ24FW							A	A	A	A	A		A	A							
RJ24FX									A												

Figure 1