



## **Bourns® Model SM13043EL Signal Transformer Module**

## Manufacturing Process Change

*Riverside, California* – May 27, 2021 – REVISED JUNE 12, 2021 – Effective immediately, Bourns will change the manufacturing process for the Model SM13043EL Signal Transformer module from manual coil winding to an automated winding process for all four sets of transformer coils incorporated into the module. This change will improve the productivity, quality and reliability of the signal transformer module.

## **Affected Part Number**

## SM13043EL

The form, fit and function of the signal transformer module remain unchanged. The quality and reliability should be improved as a result of the manufacturing process change.

Samples are available upon request.

If you have any questions or need additional information, please feel free to contact <u>Customer Service/</u><u>Inside Sales</u>.

Users should verify that the described changes will not impact the performance of the product in their specific applications.