

PRODUCT CHANGE NOTIFICATION



Bourns® Model RL895-223K-TR60-RC Radial Lead RF Choke

Addition of Manufacturing Plant

Riverside, California – June 25, 2021 – Effective July 11, 2021, an additional manufacturing plant in China will produce the <u>Model RL895-223K-TR60-RC Radial Lead RF Choke</u> to accommodate increasing production demands.

Affected Part Number

RL895-223K-TR60-RC

No design, material or manufacturing process changes for this Radial Lead RF Choke will be made at the new plant. The form, fit, function, country of origin, quality, reliability and production lead time of this part number will remain the same.

Implementation dates are as follows:

Date that production will begin at the new plant: *July 11, 2021*

First date code using the above changes: 2128

If you have any questions or need additional information, please feel free to contact <u>Customer Service/</u><u>Inside Sales</u>.

IC2165

Asia-Pacific: Tel +886-2 256 241 17