
Product Change Notification

TRANSFORMERS



January, 2016

Bourns® Model SM-LP-5001 and SM-LP-5002 Series Surface Mount Line Matching Transformers Change to Carrier Tape Specifications

Bourns has decided to change the carrier tape specifications for the Model SM-LP-5001 and SM-LP-5002 Series Surface Mount Line Matching Transformers. The carrier tape has been redesigned to help limit lateral movement of the component to within 1 mm in compliance with the EIA-481-D Standard. The form, fit and function of the transformer will remain the same. Specifications of the carrier tape are provided on the following page.

Affected Part Numbers
SM-LP-5001E
SM-LP-5001MEL
SM-LP-5002E
SM-LP-5002E-40


Implementation dates are as follows:

Date that manufacturing of existing packaging will cease: **July 2, 2016** Date that deliveries of modified packaging will begin: **July 3, 2016** First date code using the new packaging: **1628**

If you have any questions or need additional information, please feel free to contact Customer Service/Inside Sales.


Change to Carrier Tape Specifications

Existing Tape Carrier Dimensions



ITEM F Ε D D1 PO P2 W A0 B0 K0 P Т 24.00 +0.30 10.50 +0.10 14.30 +0.10 7.70 +0.10 16.00 ^{+0.10}_{-0.10} 11.50 ^{+0.10}_{-0.10} 1.75 +0.10 1.50 +0.10 1.50 +0.10 $4.00^{+0.10}_{-0.10}$ 2.00 +0.10 $0.40^{+0.05}_{-0.05}$ DIM

Modified Tape Carrier Dimensions



ITEM	W	A0	ВО	КО	Р	F	E	D0	D1	P0	P2	Т	A1	K 1
DIM	24.00 ^{+0.30} _{-0.10}	9.50 ^{+0.10} _{-0.10}	14.95 ^{+0.10}	7.90 ^{+0.10}	16.00 ^{+0.10}	11.50 ^{+0.10}	1.75 +0.10	1.50 +0.10	2.00 +0.10	4.00 +0.10	2.00 +0.10	0.50 +0.05	6.92 +0.10	7.50 ^{+0.10}