


Product Change Notification

INDUCTIVE COMPONENTS


Bourns Manufacturers Representatives
Corporate Distributor Product Managers
Americas Sales Team
Asia Sales Team
Europe Sales Team
Bourns Internal
Bourns Plant Managers



April, 2011

Component Marking Change on Line Matching Transformer SM-LP-500x Models

Effective with manufacturing date code 1125, Line Matching Transformer Model SM-LP-500x component nomenclature marking will be changed. The C-UL-US Component Recognition product safety agency logo will appear on new manufactured parts.



Current Marking



New Marking

Affected P/Ns: [SM-LP-5001](#)(E, SE), [SM-LP-5002](#)(E)

If you have any questions, please contact [Bourns Customer Service](#).