



PRODUCT OBSOLESCENCE MEMO

ROTARY POTENTIOMETERS



Bourns® Model 0037 Series Rotary Potentiometer to be Discontinued

Riverside, California – April 16, 2020 – In accordance with our ongoing product lifecycle management procedure, Bourns is transferring the Model 0037 Rotary Potentiometer to an End of Life status. Low volume production necessitates this action.

Obsolete Part Numbers			
0037-001-AB103	0037-044-AB472	0037-045-AB222	0037-056-AB474
0037-006-AB103	0037-049-AB103	0037-052-AB222	0037-057-AB474
0037-017-AB103	0037-023-AB104	0037-034-AB474	0037-033-AB473
0037-044-AB103	0037-007-AB222	0037-033-AB474	0037-044-AB473

Regrettably, no replacement product is available at this time. Customers must notify Bourns in writing within 30 days of receipt of this notification if they consider the discontinued product to be “sole sourced” by Bourns. In such cases, Bourns will work with customers to negotiate an appropriate end-of-life purchase for the discontinued product. Products purchased during this End of Product Life transition period will be covered by Bourns’ standard warranty. Last Time Buy orders for this model will be considered non-cancellable and non-returnable.

Please plan for the following deadlines:

Last time buy date: **October 14, 2020**

Last time ship date: **April 14, 2021**

Should you have any questions or need additional information, please feel free to contact [Customer Service/Inside Sales](#).

SC2024