BOURNS

Product Obsolescence Memo

TBU® HIGH-SPEED PROTECTORS

June, 2014



Bourns® Model P500-G Series TBU® High-Speed Protectors to be Discontinued

In accordance with our ongoing product lifecycle management procedure, Bourns has identified select TBU° High-Speed Protector products that will be transferred to an End of Product Life status. The Bourns° Model P500-G Series Dual TBU° High-Speed Protectors will be discontinued due to a lack of sales volume and diminishing demand.

Bourns suggests the Model TBU-PL series as the replacement part numbers for VoIP applications and the Model P850-G for other applications. Please contact the Bourns team of Field Application Engineers if you have any questions regarding the suggested replacement part numbers and your application requirements.

Products purchased during this End of Product Life transition period will be covered by Bourns' standard warranty. Last Time Buy orders for the discontinued products will be considered non-cancellable and non-returnable.

Obsolete Part Numbers	Replacement Part Numbers For VoIP Applications
P500-G120-WH	TBU-PL050-100-WH
P500-G200-WH	TBU-PL050-200-WH

Obsolete Part Numbers	Replacement Part Numbers For Other Applications
P500-G120-WH	P850-G120-WH
P500-G200-WH	P850-G200-WH

Please plan for the following deadlines:

Last time buy date: April 30, 2015 Last time ship date: June 30, 2015

Should you have any questions or need additional information, please feel free to contact Customer Service/Inside Sales.